



Saint Joseph River Watershed
 Fish Migration Barrier Inventory

Legend

- ◆ Dam- Inspected High Priority for Removal/Modification
- ◆ Low Priority for Removal
- ◆ Removal in Progress
- ✕ No Longer Exists/Functions
- ⬠ Dam- No Inspection
- St. Joseph River Watershed
- Culvert Inspection Subwatershed

Drawn By: MCL
 Designer: MCL
 Reviewer: EWO
 Manager: EWO

Hard copy is intended to be 24"x36" when plotted. Scale(s) indicated and graphic quality may not be accurate for any other size.

PROJECT NO.
G100404

SHEET NO.

PLOT INFO: UC:\ADD\100404\GMAP_DOCUMENT\WALL MAP INSPECTION.LXD DATE: 12/29/2011 USER: MCL